

HD 21. FILE  
No. 58

Anchorage, Alaska  
October 31, 1951

To: R. H. Bruce, Ass't Supt. of Operations  
From: Roy V. Boyd, Supt. of Operations  
Subj: AX report No. 246

Reference is made to accident where Engine 556 backed into Caboose No. 1020, causing damage. This accident occurred at Tunnel on October 29, 1951.

Please arrange to hold hearing on this matter as soon as possible and when hearing is held request a Road Foreman of Engines to be present.

*COPY*  
*Roy V. Boyd*  
Roy V. Boyd

RVB:gk  
cc-John E. Manley  
G. A. Benedict

NOV 1 1951  
ANCHORAGE, ALASKA